




2 A




American Style



2 B




European Style



! IEC Pollution Degree II


3 A

American Style




3 B

European Style



4



Cables enter from left side

Les câbles entrent par le côté gauche

Kabeldurchführung von links

Los cables entran por el lado izquierdo

Inserire i cavi dal lato sinistro

Kabelinvoer vanaf de linkerzijde

電源/データケーブルは左側から入ります

电源线/数据线从左侧进入

تدخل الكابلات من الجانب الأيسر

Service switch

Interrupteur de service

Wartungsschalter

Interruptor de servicio

Interruttore di servizio

Serviceschakelaar

サービススイッチ

服务开关

زر الخدمات





5




DDNP1501

DMNP24040-P-NA



THIRD PARTY



Required Supply: SELV/Class 2 (UL)
12 V \equiv 500 mA
24 V \equiv 300 mA




RS-485 DyNet
SELV/Class 2 (UL)




IEC Overvoltage Category III


6




7







8



9



Clean only with a clean damp cloth.
DO NOT use corrosive or harsh cleaning agents



⚠ Do not connect inputs to mains.

⚠ Refer to Service Guide for full cleaning recommendations.

⚠ Caution – risk of explosion if battery is replaced by an incorrect type.

⚠ Attention – risque d'explosion si la pile est remplacée par un Type incorrect.

⚡ **Federal Communications Commission (FCC) Compliance Notice: Radio Frequency Notice** – This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures: Reorient or relocate the receiving antenna. Increase the separation between the equipment and receiver. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected. Consult the dealer or an experienced radio/TV technician for help. Any modifications not approved by the manufacturer of this device could void the user's authority to operate this device.

⚡ This Class B digital apparatus complies with Canadian ICES-003: CAN ICES-3(B)/NMB-3(B). Cet appareil numérique de la Classe B est conforme à la norme NMB-003 du Canada: CAN ICES-3(B)/NMB-3(B).

⚡ Installation of a home and building automation and control system shall comply with IEC 60364 (all parts). The temperature limits and current-carrying capacities for the communication wires specified in IEC 60364-5-52 shall not be exceeded.